


FIG. 1



—▲— CONDITION(2)  
--x-- CONDITION(3)

FIG. 2

FIG. 3




FIG. 4




FIG.5A

$Y = 0.00$




FIG.5B

$Y = 0.02$   
( $W = 1.30$ )




FIG.5C

$Y = 0.05$   
( $W = 2.70$ )




FIG.5D

$Y = 0.07$   
( $W = 4.00$ )




FIG.6A

$Y = 0.00$




FIG.6B

$Y = 0.02$   
( $W = 1.30$ )




FIG.6C

$Y = 0.05$   
( $W = 2.70$ )




FIG.6D

$Y = 0.07$   
( $W = 4.00$ )





FIG. 7

FIG. 8




FIG. 9




FIG.10A

$Y = 0.00$




FIG.10B

$Y = 0.15$   
( $W = 8.50$ )




FIG.10C

$Y = 0.29$   
( $W = 17.00$ )




FIG.10D

$Y = 0.43$   
( $W = 25.50$ )




FIG.11A


 $Y = 0.00$ 

FIG.11B


 $Y = 0.15$   
( $W = 8.50$ )

FIG.11C


 $Y = 0.29$   
( $W = 17.00$ )

FIG.11D



 $Y = 0.43$   
( $W = 25.50$ )

FIG.12




FIG.13




FIG.14



FIG.15




FIG.16




FIG.17A

$Y = 0.00$




FIG.17B

$Y = 0.02$   
( $W = 1.30$ )




FIG.17C

$Y = 0.05$   
( $W = 2.70$ )




FIG.17D

$Y = 0.07$   
( $W = 4.00$ )




FIG.18A

$\gamma = 0.00$




FIG.18B

$\gamma = 0.02$   
( $W = 1.30$ )




FIG.18C

$\gamma = 0.05$   
( $W = 2.70$ )




FIG.18D

$\gamma = 0.07$   
( $W = 4.00$ )





FIG.19

FIG.20







FIG.21




Y= 0.00  
FIG.22A



Y= 0.14  
(W= 7.90 )  
FIG.22B



Y= 0.27  
(W=15.70 )  
FIG.22C



Y= 0.40  
(W=23.60 )  
FIG.22D




FIG.23A


 $Y = 0.00$ 

FIG.23B


 $Y = 0.14$   
( $W = 7.90$ )

FIG.23C


 $Y = 0.27$   
( $W = 15.70$ )

FIG.23D



 $Y = 0.40$   
( $W = 23.60$ )

FIG.24




FIG.25




FIG.26




FIG.27

FIG.28






FIG.29




FIG.30A

Y= 0.00




FIG.30B

Y= 0.05  
(W= 3.10 )




FIG.30C

Y= 0.11  
(W= 6.10 )




FIG.30D

Y= 0.16  
(W= 9.20 )




FIG.31A

$Y = 0.00$




FIG.31B

$Y = 0.05$   
( $W = 3.10$ )




FIG.31C

$Y = 0.11$   
( $W = 6.10$ )




FIG.31D

$Y = 0.16$   
( $W = 9.20$ )





FIG.32




FIG.33




FIG.34




FIG.35

FIG.36




FIG.37




FIG.38A

Y= 0.00




FIG.38B

Y= 0.05  
(W= 2.90 )




FIG.38C

Y= 0.10  
(W= 5.80 )




FIG.38D

Y= 0.15  
(W= 8.60 )




FIG.39A


 $Y = 0.00$ 

FIG.39B


 $Y = 0.05$   
( $W = 2.90$ )

FIG.39C


 $Y = 0.10$   
( $W = 5.80$ )

FIG.39D



 $Y = 0.15$   
( $W = 8.60$ )

FIG.40




FIG.41




FIG.42




FIG.43

FIG.44






FIG.45




FIG.46A

Y= 0.00




FIG.46B


Y= 0.05  
(W= 2.90 )

FIG.46C


Y= 0.10  
(W= 5.80 )

FIG.46D


Y= 0.15  
(W= 8.60 )

FIG.47A


 $Y = 0.00$ 

FIG.47B


 $Y = 0.05$   
( $W = 2.90$ )

FIG.47C


 $Y = 0.10$   
( $W = 5.80$ )

FIG.47D



 $Y = 0.15$   
( $W = 8.60$ )

FIG.48




FIG.49